UNITROL 1000 Application Notes 1310_0255

CMT 1000 Vulnerability bug fix

Summary

A third party component, which is used in CMT UN1000 software for Windows PCs, is vulnerable to ActiveX execution.

An attacker who successfully exploits this vulnerability could run arbitrary code on a computer where the product is installed.

The security of the affected PC can be reestablished by installing the latest CMT 1000 Release 6.101.

ABB recommends to install the latest CMT1000 Release 6.101 to secure your PC against hacker attacks.

	UNITROL 1000-15 Status Serial no	UNITROL 1000-7 Status Serial no
Hardware Version	 ✓ UNITROL 1020 Status Serial no ✓ UNITROL 1000-PM40 Status Serial no 	UNITROL 1010 Status Serial no
	Panel SW	NA
Software Version	Target SW	NA
	CMT 1000	4.xxx / 5.xxx / 6.xxx

Based on			Project	UNITE	ROL 10	00		
Prepared by	Rudolf Moeckli 29	9.10.13	AN 1310_0255					
Approved by	Rene Pulfer 29	.10.13	Responsible Department	ATPE				
Title UNITROL 1000 Application Notes, Title								
		Document number			Language	Rev. ind.	Page	1
ABB	ABB Switzerland Ltd	3BF	IS538288 E08		en	-	Number of pages	6

Table of Contents

TABLE OF CONTENTS	2
CHAPTER 1 - PROBLEM DESCRIPTION	3
1.1. Problem overview	3
1.3. Vulnerability details	3
CHAPTER 2 - SOLUTIONS	4
2.1. How to solve	4
2.1.1. Installation of different Releases	4 4
2.2. Download latest CMT	4
CHAPTER 3 - URGENCY OF ACTION(S)	6
REVISION	6

Chapter 1 - Problem Description

1.1. Problem overview

A third party component, which is used in the CMT UN1000 software for Windows PCs, is vulnerable to ActiveX execution.

An attacker who successfully exploits this vulnerability could run arbitrary code on a computer where the product is installed.

1.2. Affected applications

Affected are all PC's where the CMT1000 SW is installed. Practically all following releases are affected:

- Release 4.xxx (UNITROL 1000-15 / UNITROL 1000-7)
- Release 5. xxx (UNITROL 1000-15 / UNITROL 1000-7)
- Release 6.xxx (UNITROL 1010 / UNITROL 1020)

The vulnerability is only affecting PC's, where CMT 1000 SW is installed. UNITROL 1000 applications in operations are not affected.

1.3. Vulnerability details

The vulnerability originates from a third party ActiveX component that can allow component execution on the affected PC.

An attacker can build a website that exploits this ActiveX control to download files to any location accessible by the user.

40		Document Nr.	Language	Rev. Ind.	page
ABB	ABB Switzerland Ltd	3BHS538288 E08	en	-	3

Chapter 2 - Solutions

2.1. How to solve

Vulnerability can be solved by installing the latest CMT 1000 Release 6.101. The tool includes a batch to reestablish security of the PC.

2.1.1. Installation of different Releases

Installation of several different CMT 1000 releases are possible. In case you have older CMT1000 release (4.xxx / 5.xxx / 6.0xx) installed, you have to install only the latest CMT 1000 Release 6.101. The older versions are still full functional.

2.1.2. Compatibility

Latest CMT 1000 Release 6.101 is only working with Target Release 6.xxx. Target main release number (e.g. 5.xxx) must fit to main release of CMT 1000 (e.g. 5.xxx).

Therefore older CMT 1000 SW releases should not be deinstalled.

2.2. Download latest CMT

ABB provides accessibility to the database via internet for customers to access brochures, manuals, and SW. The database access is managed by user name and password. The password is valid for 1 month after distributing this application note.

In case the time is escalated and access with the given password is blocked, contact UNITROL 1000 support line:

unitrol1000support@ch.abb.com

		Document Nr.	Language	Rev. Ind.	page
ABB	ABB Switzerland Ltd	3BHS538288 E08	en	-	4


Access information to download CMT1000

Web link: http://domino.de.abb.com/db/db0007/db002796.nsf/Home.xsp

User name: 1000_EXT Password: GE9cKlfBlq

Navigate within database to download the CMT 1000:

- Select Filter "By Product"
- Open Folder "UNITROL 1010/1020"
- Open Folder "SW Releases / Release 6 / CMT1000



Chapter 3 - Urgency of action(s)

\square A) Information only => No special action necessary
☐ B) Fix it when occurring
☑ C) Fix it at next occasion (Factory Testing, Commissioning, Site Service)
D) Fix it proactively - Inform customer and define date when case can be
☐ E) Same as D) but additionally
Send action plan to PRUInform PRU when action(s) are completed

REVISION

Rev. ind.	Page (P) Chapt.(C)	Description	Date Dept./Init.
-	All		29.10.13 R. Moeckli ATPE-PM

45		Document Nr.	Language	Rev. Ind.	page
ABB	ABB Switzerland Ltd	3BHS538288 E08	en	-	6